



Teddington - 2021 Ward Works and Tree Removals Programme

Introduction

A recent survey of trees in the Teddington ward has taken place; this was conducted by a competent specialist Arboriculturist as part of the scheduled 4 yearly detailed inspection regime that has been devised for all Council highway and parks trees.

This cycle of inspection is in place to ensure that the Council is compliant with the statutory duties as highlighted within the adopted policy:

[Council-owned tree management policy - London Borough of Richmond upon Thames](#)

As a result of the Teddington ward survey, 622 individual tree work operations have been specified, this includes various pruning works.

Unfortunately and as to be expected with such an extensive survey of trees of varying age and condition, we have identified a number of trees that can no longer be safely retained and will therefore be carrying out complete removal. The Council will be planting a replacement for every tree that is being removed over the course of the 2022-23 planting season, which runs from this November through to March of next year.

Removal will be prioritised as appropriate and take place over the course of the next 8 weeks, we will be erecting notices upon each tree to alert the public to the proposed removal, giving sufficient time for residents to log enquiries.

Prior to the removals taking place, signage will be erected informing of a date of works, this is to make vehicle owners aware of the need to leave parking spaces free to allow the works to proceed in a safe and timely manner.

The following pages provide the locations of each tree that is to be removed, in addition photographs and inspection findings have been provided.

Dated 09.03.2021

Contents

Site 1.	Arlington Road	3
Site 2.	Avenue Gardens	6
Site 3.	Blackmores Grove	7
Site 4.	Bushy Park Road	11
Site 5.	Cambridge Crescent	13
Site 6.	Cedar Road	14
Site 7.	Claremont Road	15
Site 8.	Clarence Road	20
Site 9.	Coleshill road	Error! Bookmark not defined.
Site 10.	Elmfield Avenue	Error! Bookmark not defined.
Site 11.	Gomer Gardens	Error! Bookmark not defined.
Site 12.	Grove Gardens	3
Site 13.	High Street	7
Site 14.	Linden Grove	11
Site 15.	Manor Road	13
Site 16.	Shaef Way	14
Site 17.	St marys Avenue	15
Site 18.	Teddington Park Road	20
Site 19.	Twickenham Road	Error! Bookmark not defined.
Site 20.	Vicarage Road	Error! Bookmark not defined.
Site 21.	Waldegrave Road	Error! Bookmark not defined.

Site 1. Arlington Road

Tree number	9
Park	Arlington Road
Location	Outside 23
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	7.00
Physiological condition	Poor
Structural condition	Fair
Inspection findings	Ganoderma spp decay pathogen fruiting body at base and half of crown is already dead including a major scaffold limb. Remaining crown beginning to die back and presents no real scope for remedial reduction as this (given species tendencies) is likely to kill the remaining tree

Site image



Image shows half of tree devoid of live growth and leaving no viable remedial pruning options

Tree number	6
Park	Arlington Road
Location	Outside 69-71
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	6.50
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Ganoderma species fungal bodies at base, tree crown is uniformly thinning out with reduced leaf size and density. There is a moderate lean in the main stem which obstructs free passage on pathway. Although relatively young its issues cannot be satisfactorily be remedial via pruning

Site image




Image shows lean in stem towards properties and minimum required pavement clearances not possible at present



Image shows fruiting bodies of the decay pathogen Ganoderma spp at 2 separate basal locations

Site 2. Avenue Gardens

Tree number	8
Road	Avenue Gardens
Location	Outside 5-7
Species	Serviceberry (<i>Amalanchier</i> sp.)
Height	3.5 meters
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Tree has poorly established root system and is loose in ground, reduced leaf size and crown density, apical growth dieback. ie. physiologically declining

Site images



Image shows reduced crown density and limited but uniform dieback. Tree is also structurally compromised through poor root establishment

Site 3. Blackmores Grove

Tree number	15
Road	Blackmores Grove
Location	Opposite 5
Species	Mountain Ash (<i>Sorbus aucuparia</i>)
Height	6.00
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Images show dead tree during peak growing season

Tree number	28
Road	Blackmores Grove
Location	Adjacent to 59 Station Road
Species	Unknown
Height	5.00
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows young dead tree on footpath during peak growing season

Tree number	24
Road	Blackmores Grove
Location	Outside 61
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	6.50
Physiological condition	Good
Structural condition	Poor
Inspection findings	Proliferation of Gannoderma fruiting bodies around base. Resonance tests indicated advancing decay. Structurally compromised. No scope for adequate sail reduction given spp

Site image:





Images show both young and mature *Gannoderma* spp fruiting bodies around base. Clear indications of internal decay

Site 4. Bushy Park Road

Tree number	32
Road	Bushy Park Road
Location	Outside 41
Species	Bird cherry (<i>Prunus padus</i>)
Height	2.5
Physiological condition	Good
Structural condition	Poor
Inspection findings	Ganoderma spp brackets present at base and presenting an extensive basal cavity with limited holding wood opposing stem lean. Higher the acceptable risk of failure

Site image:



Image shows area of extensive internal basal decay. While not clearly visible externally, probing and resonance tests have found the structural integrity is compromised with a raised risk of failure

Tree number	24
Road	Bushy Park Road
Location	Outside 1-3
Species	Japanese Privet (<i>Ligustrum japonicum</i>)
Height	5.5
Physiological condition	Good
Structural condition	Poor
Inspection findings	Tree doesn't have established rooting system and is leaning over with potential for failure over path and / or road.

Site image:



Image shows acute lean in stem arising from poor root establishment / stability

Site 5. Cambridge Crescent

Tree number	7
Road	Cambridge Crescent
Location	Outside 89
Species	Crab apple (<i>Malus spp</i>)
Height	6.50
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Ganoderma and extensive basal cavity. Bole decayed out beneath root collar, failure potential as no significant amount of quality holding wood remaining

Site image:



Image shows extensive basal cavity/hollowing with *Ganoderma spp* pathogen fruiting bodies within

Site 6. Cedar Road

Tree number	4
Road	Cedar Road
Location	Outside 10-12
Species	Norway Maple (<i>Acer platanoides</i>)
Height	5.00
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows dead young transplant which failed to come out of dormancy

Site 7. Claremont Road

Tree number	18
Road	Claremont Road
Location	Outside 2A
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	7.5
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Phellinus pomaceus brackets at base of stem and around upper stem, with internal decay defects in base of stem when using sounding hammer. Poor structural integrity and showing partial crown dieback. This decay fungus has a high incidence of failure in this tree species

Site image:





Images show two of several areas on the stem with decay pathogen fruiting bodies. Colonisation of this species often leads to failure of trees in part or whole

Tree number	22
Road	Claremont Road
Location	Outside 21-23
Species	Crab Apple (<i>Malus spp</i>)
Height	7.50
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Ganoderma species fungal brackets at base, advanced stem decay; resonating as hollowed out. Apical die off, tree has a limited useful life expectancy remaining. Assessing officer also reports excessive movement in stem


Site image:



Image shows area of hollowed stem with 20cm+ screwdriver probed. Quality of wood in this area is degraded and compromised in terms of structural stability

Tree number	8
Road	Claremont Road
Location	Outside 30
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	7.00
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Strip of necrotic wood up stem from base, extensive decay progressing into stem. A resonance test revealed an unacceptable degree of decay in the trunk of this tree, removal is required to prevent natural failure and manage risk.


Site image:



Images shows tree in situ and area of decay indicated by resonance testing

Tree number	7
Road	Claremont Road
Location	Outside 36
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	7.5m
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Fungal fruiting bodies of the wood decay fungus <i>Laetiporus sulphureus</i> are present on the trunk of this tree. This fungus causes a brown rot which can rapidly reduce wood strength and cause branch or whole tree failure through brittle fracture.

Site image:



Images shows tree in situ and probe inserted into decayed wood adjacent to remnants of fungal fruiting body.

Site 8. Clarence Road

Tree number	25
Road	Clarence Road
Location	Outside 59
Species	Horse Chestnut (<i>Aesculus hippocastanum</i>)
Height	14.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	This tree has stem bleeding, necrotic bark and crown die back which is consistent with the pathogen <i>Pseudomonas syringae</i> . The extent of infection has permanently damaged this trees adaptive capacities and it now presents an unacceptable risk and requires removal.

Site image:



Left image shows tree with sparse canopy on the road side, right image shows main crown break with stem bleeding, necrotic bark and saprotrophic fungi colonising dead tissue.

Site 9. Coleshill Road

Tree number	18
Road	Coleshill Road
Location	Outside 41-43
Species	Swedish Whitebeam (<i>Sorbus intermedia</i>)
Height	8.0m
Physiological condition	Poor
Structural condition	Fair
Inspection findings	This tree is in a state of physiological decline and contains weak branches that are liable to collapse.

Site image:



Image shows tree with sparse canopy

Tree number	24
Road	Coleshill Road
Location	Outside 77
Species	Bird Cherry (<i>Prunus padus</i>)
Height	6.0m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	An emerging fungal fruiting body displaying characteristics of decay pathogen <i>Ganoderma</i> sp. is present at the stem base. Colonisation by this fungus causes a white rot of the stem and root system that can cause entire trees to collapse through fracture or windthrow. The tree is declining, significant dieback is present and this correlates with the pathogen present.

Site image:



Image shows tree with sparse canopy

Site 10. Elmfield Avenue

Tree number	14
Road	Elmfield Avenue
Location	Outside 38
Species	Apple (<i>Malus</i> sp.)
Height	5.0m
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Tree main trunk and roots are decayed; tree is moving in such a way that indicates that the structure is compromised presenting increased risk of failure. Crown dieback could correlate with the degradation of the trees structural or supporting root system.

Site image:



Image shows tree with sparse canopy and lean towards road

Tree number	28
Road	Elmfield Avenue
Location	Outside 27
Species	Cherry (<i>Prunus</i> sp.)
Height	7.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	This tree is in a state of physiological decline and contains weak branches that are liable to collapse.

Site image:



Image shows tree with extensive die back of canopy

Site 11. Gomer Gardens

Tree number	4
Road	Gomer Gardens
Location	Outside 4/6
Species	Cherry (<i>Prunus</i> sp.)
Height	5.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	Tree trunk and roots are extensively decayed/damaged; tree is moving in such a way that indicates that the structure is compromised presenting increased risk of failure. Crown dieback could correlate with the degradation of the trees structural or supporting root system.


Site image:



Left image shows tree with die back of canopy. Right image shows basal damage.

Tree number	5
Road	Gomer Gardens
Location	Outside 2
Species	Cherry (<i>Prunus</i> sp.)
Height	5.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	The trunk and base of this tree contain cavities and splits. A resonance test revealed an unacceptable degree of decay in the trunk of this tree; this decay correlates with crown dieback and decline. Removal is required to prevent natural failure and manage risk.

Site image:



Left image shows tree with die back of canopy. Right image shows split in trunk.

Site 12. Grove Gardens

Tree number	4
Road	Grove Gardens
Location	Grove Gardens – need map
Species	Spruce (<i>Picea</i> sp.)
Height	11.0m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	A cavity indicating root and lower stem decay is present at the base of this tree; this decay correlates with crown dieback and decline.

Site image:



Image shows tree with die back of canopy and basal decay

Tree number	21
Road	Grove Gardens
Location	Grove Gardens – need map
Species	Lawsons Cypress (<i>Chamaecyparis lawsoniana</i>)
Height	12.5m
Physiological condition	Poor
Structural condition	Good
Inspection findings	This tree is dying/deadwood is ubiquitous

Site image:



Left image shows tree with die back of canopy. Right image shows split in trunk.

Tree number	26
Road	Grove Gardens
Location	Grove Gardens – need map
Species	Silver Birch (<i>Betula pendula</i>)
Height	13.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	There is a cavity indicating decay at the base of this tree. A resonance test confirmed an unacceptable degree of decay in the trunk of this tree; this decay correlates with crown dieback and decline. Removal is required to prevent natural failure and manage risk.

Site image:



Image shows tree with sparse foliage.

Site 13. High Street

Tree number	20
Road	High Street
Location	Outside 2
Species	Cherry (<i>Betula papyifera</i>)
Height	11.0m
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and manage risk.

Site image:



Image shows dead tree.

Site 14. Linden Grove

Tree number	3
Road	Linden Grove
Location	Opposite 6
Species	Apple (<i>Malus</i> sp.)
Height	6.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	Fungal fruiting bodies of the decay pathogen <i>Ganoderma</i> sp. are present at the stem base and the trunk. Colonisation by this fungus causes a white rot of the stem and root system that can cause entire trees to collapse through fracture or windthrow. Tree is declining, significant deadwood and dieback is present and this correlates with the pathogen present.

Site image:



Left image shows tree with die back of canopy. Right image shows fungal fruiting bodies at base.

Site 15. Manor Road

Tree number	11
Road	Manor Road
Location	Manor Road Recreation Ground – need map
Species	Horse Chestnut (<i>Aesculus hippocastanum</i>)
Height	7.0m
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows dead tree.

Tree number	26
Road	Manor Road
Location	Manor Road Recreation Ground – need map
Species	Hornbeam (<i>Carpinus betulus</i>)
Height	3.5m
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows dead tree.

Tree number	27
Road	Manor Road
Location	Manor Road Recreation Ground – need map
Species	Foxglove Tree (<i>Paulonia tomentosa</i>)
Height	7.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	This tree is dying/deadwood is ubiquitous

Site image:



Image shows tree with extensive die back of canopy.

Site 16. Shaef Way

Tree number	2
Road	Shaef Way
Location	On Grass Area Outside 30
Species	Wild Cherry (<i>Prunus avium</i>)
Height	12.5m
Physiological condition	Good
Structural condition	Poor
Inspection findings	A fungal fruiting body of the decay pathogen <i>Ganoderma</i> sp. is present at the stem base. Colonisation by this fungus causes a white rot of the stem and root system that can cause entire trees to collapse through fracture or windthrow. Fungal fruiting bodies of the wood decay fungus <i>Laetiporus sulphureus</i> are present on the trunk of this tree. This fungus causes a brown rot which can rapidly reduce wood strength and cause branch or whole tree failure through brittle fracture.

Site image:



Left image shows tree in apparent good vitality. Right image shows fungal fruiting bodies at base.

Tree number	11
Road	Shaef Way
Location	On Grass Verge Opposite 62
Species	Unknown dead
Height	3.5m
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows dead tree.

Site 17. St Marys Avenue

Tree number	4
Road	St Marys Avenue
Location	Opposite 12
Species	Silver Birch (<i>Betula pendula</i>)
Height	7.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	Cavities indicating decay are present in the trunk of this tree. This tree is in a state of physiological decline with sparse foliage and ubiquitous deadwood.

Site image:



Left image shows tree with die back of canopy. Right image shows split in trunk.

Site 18. Teddington Park Road

Tree number	19
Road	Teddington Park Road
Location	Outside 104
Species	Cherry (<i>Prunus</i> sp.)
Height	3.5m
Physiological condition	Poor
Structural condition	Poor
Inspection findings	This tree is in a state of physiological decline with sparse foliage and ubiquitous deadwood.

Site image:



Image shows tree with die back of canopy.

Tree number	20
Road	Teddington Park Road
Location	Outside 94/96
Species	Cherry (<i>Prunus</i> sp.)
Height	5.5m
Physiological condition	Fair
Structural condition	Poor
Inspection findings	A fungal fruiting body of the decay pathogen <i>Ganoderma</i> sp. is present at the stem base. Colonisation by this fungus causes a white rot of the stem and root system that can cause entire trees to collapse through fracture or windthrow.

Site image:



Left image shows tree with mainly healthy canopy. Right image highlights fructifications.

Site 19. Twickenham Road

Tree number	16
Road	Twickenham Road
Location	Outside 79
Species	Whitebeam (<i>Sorbus aria</i>)
Height	6.5m
Physiological condition	Fair
Structural condition	Poor
Inspection findings	The trunk of this tree contains cavities and splits. Fungal fruiting bodies of the decay pathogen <i>Kretzschmaria deusta</i> are present in the cavity. This fungus causes a white rot that can cause whole tree failure through a ceramic like fracture. Removal is required to prevent natural failure and manage risk.

Site image:



Left image shows tree with die back of canopy. Right image shows split in trunk.

Site 20. Vicarage Road

Tree number	9
Road	Vicarage Road
Location	Opposite 17
Species	Lime (<i>Tilia</i> sp.)
Height	9.0m
Physiological condition	Good
Structural condition	Poor
Inspection findings	A fungal fruiting body of the decay pathogen <i>Ganoderma</i> sp. is present at the stem base. Colonisation by this fungus causes a white rot of the stem and root system that can cause entire trees to collapse through fracture or windthrow.

Site image:



Left image shows tree with healthy canopy. Right image shows fungal fruiting body at base.

Tree number	-
Road	Vicarage Road
Location	Wade Lane Ground Play Area- Need Map
Species	Silver Birch (<i>Betula pendula</i>)
Height	2.0m
Physiological condition	Dead
Structural condition	Dead
Inspection findings	This tree is dead and removal is required to prevent natural failure and facilitate replanting.

Site image:



Image shows dead tree.

Tree number	-
Road	Vicarage Road
Location	Wade Lane Ground Play Area- Need Map
Species	Sycamore (<i>Acer pseudoplatanus</i>)
Height	5.5m
Physiological condition	Good
Structural condition	Poor
Inspection findings	This tree is regrowing from a stump and is in an unsuitable location.

Site image:



Left image shows tree with die back of canopy. Right image shows split in trunk.

Site 21. Waldegrave Road

Tree number	15
Road	Waldegrave Road
Location	Outside 99 The Naylor Library on South East side of front entrance
Species	Italian Alder (<i>Alnus cordata</i>)
Height	19.0m
Physiological condition	Poor
Structural condition	Fair
Inspection findings	This tree is in a state of physiological decline and crown dieback is likely to correlate with the degradation of the trees structural or supporting root system.

Site image:



Image shows tree with die back of canopy.

Tree number	25
Road	Waldegrave Road
Location	Opposite 12
Species	Italian Alder (<i>Alnus cordata</i>)
Height	11.0m
Physiological condition	Fair
Structural condition	Poor
Inspection findings	Cavities indicating decay are present in the trunk of this tree. A resonance test revealed an unacceptable degree of decay in the trunk of this tree, removal is required to prevent natural failure and manage risk.

Site image:



Left image shows tree with tip die back of canopy. Right image shows cavity in base with probe inserted.