



April 2026 - Reactive Tree Works Programme

Introduction

A survey of trees in the North Richmond and Teddington wards are currently being undertaken; this is being conducted by specialist arboricultural officers as part of the scheduled 4 yearly detailed inspection regime that has been devised for all Council highway and parks trees.

On a monthly basis the Council's arboricultural officers undertake tree assessments that sit outside of the scheduled 4 yearly inspection programme, generally this is in response to customer enquiries.

These inspections take place to ensure that Council is compliant with the statutory duties which are highlighted within the [Council's Adopted Tree Policy](#).

Recent reactive inspections have identified the need for 58 individual tree work operations to take place. This work will now be issued to the Council's Arborist Contractor KPS, for completion over the spring period.

Unfortunately, and as to be expected with surveys of a large treestock with specimen of varying age and condition, we have identified trees that can no longer be safely retained, and we will therefore be carrying out complete removal. The Council will aim to plant replacement trees during the next planting season which runs from November through to March; in some instances, this timing of planting may be affected by the available Highway Management resources that are required to repair disrupted pavements.

We will be erecting notices upon each tree being removed, alerting the public to the proposals giving sufficient time for residents to log enquiries. Prior to the removal taking place signage will be erected informing of a date of works, this is to make vehicle owners aware of the need to leave any parking space free to allow the works to proceed in a safe and timely manner.

The following pages provide the locations of each tree that is to be removed, in addition photographs and descriptions of the inspection findings have been provided.

Dated 26/04/2026

Contents

<u>Barnes</u>	3
<u>Fulwell and Hampton Hill</u>	4
<u>Hampton</u>	5 - 6
<u>Hampton Wick and South Teddington</u>	7 - 9
<u>Heathfield</u>	10
<u>Kew</u>	11 - 12
<u>North Richmond</u>	13 - 32
<u>South Twickenham</u>	33 - 34
<u>Teddington</u>	35 - 66
<u>Whitton</u>	67

Barnes

Ward	Barnes
Road	Lowther Road
Location	Side of 48 Suffolk Road rear garden by garage
Species	Wild Cherry (<i>Prunus avium</i>)
Height	5.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene

Fulwell and Hampton Hill

Ward	Fulwell and Hampton Hill
Road	Burtens Road
Location	Opposite 167
Species	English oak (<i>Quercus robur</i>)
Height	13.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Hampton

Ward	Hampton
Road	Malvern Road
Location	Outside 46-48
Species	Wild cherry (<i>Prunus avium</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is leaning into the road, creating an unacceptable obstruction to highway users. Removal is required to eliminate the obstruction and facilitate replanting.

Site images:



Images show tree in street scene.



Images show leaning trunk.

Hampton Wick and South Teddington

Ward	Hampton Wick and South Teddington
Road	Fairfax Road
Location	Outside 17/19
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	3.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Hampton Wick and South Teddington
Road	Kingston Lane
Location	Opposite 23
Species	Elm (<i>Ulmus</i> sp.)
Height	12.0m
Physiological Condition	Dead
Structural Condition	fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Hampton Wick and South Teddington
Road	Munster Road
Location	Outside 78/80
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	3.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has cracked, peeling bark on the trunk, indicating necrosis and dysfunction of the trees vascular system. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene with bark damage circled.

Heathfield

Ward	Whitton
Road	Whitton Way
Location	Adjacent to 137-139 Constance Road
Species	Birch (<i>Betula sp.</i>)
Height	8.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Kew

Ward	Kew
Road	Atwood Avenue
Location	Outside 33
Species	False acacia (<i>Robinia sp.</i>)
Height	6.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity with probe circled.

North Richmond

Ward	North Richmond
Road	Manor Grove
Location	Outside 110
Species	Lebanese wild apple (<i>Malus trilobata</i>)
Height	9.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	North Richmond
Road	Clydesdale Gardens
Location	Outside 26/28
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	7.5m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the main trunk; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this particular species. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies circled.

Ward	North Richmond
Road	Tangier Road
Location	Outside 30
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	9.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.

Ward	North Richmond
Road	Tangier Road
Location	Outside 58
Species	Wild cherry (<i>Prunus avium</i>)
Height	4.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Bark damage is present on the trunk of this tree; the decline of the trees vascular system correlates with dieback within the crown. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows damage bark on trunk.

Ward	North Richmond
Road	Jocelyn Road
Location	Outside 60
Species	Bird cherry (Prunus padus)
Height	7.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows probe circled.



Image shows fungal fruiting bodies circled.

Ward	North Richmond
Road	Stanmore Road
Location	Opposite lamppost 001
Species	Cherry (<i>Prunus sp.</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	North Richmond
Road	Stanmore Road
Location	Opposite 16
Species	Higan cherry (<i>Prunus x subhirtella</i>)
Height	3.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	North Richmond
Road	Selwyn Avenue
Location	Outside 8/10
Species	Cherry (<i>Prunus sp.</i>)
Height	7.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	North Richmond
Road	Bicester Road
Location	Adjacent 189 Manor Grove main building
Species	Wild cherry (<i>Prunus avium</i>)
Height	8.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Fruiting bodies of the decay fungus Turkey Tail (<i>Trametes versicolor</i>) are prolific on the trunk and within the crown of this tree. This fungus causes a selective white rot of the wood and, when prolific, is indicative of wider physiological dysfunction, which correlates with crown dieback. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows fungal fruiting bodies circled.

Ward	North Richmond
Road	Somerton Avenue
Location	Outside 30/32
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.



Image shows fungal fruiting body circled.

Ward	North Richmond
Road	Lambert Avenue
Location	Outside 35
Species	Purple-leaf plum (<i>Prunus cerasifera</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	Fungal fruiting bodies of the decay fungi 'Honey fungus' <i>Armillaria sp.</i> are present at the base of this tree. Colonisation by this fungus causes a white rot of the roots and butt that can cause entire tree failure. Crown dieback could correlate with the parasite present. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.



Image shows fungal fruiting bodies circled.

Ward	North Richmond
Road	Manor Park
Location	Opposite 4
Species	Cherry (<i>Prunus sp.</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	North Richmond
Road	Carrington Road
Location	Adjacent to 20 Kings Farm Avenue
Species	Higan cherry (<i>Prunus x subhirtella</i>)
Height	3.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has an unacceptable amount of structural damage on the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows structural damage to stem.

South Twickenham

Ward	South Twickenham
Road	Saville Road
Location	Outside 29
Species	Wild cherry (<i>Prunus avium</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Twickenham
Road	Cross Deep
Location	Outside 96
Species	Apple (<i>Malus sp.</i>)
Height	9.0m
Physiological Condition	Good
Structural Condition	Good
Inspection findings/reason for exemption	This tree is causing an unreasonable obstruction to buses due to the truck's proximity to the kerb line and the narrow bus lane, and there are no viable pruning options. Removal is required to manage risk and facilitate replanting in a more suitable location.

Site images:



Image shows tree in street scene.

Teddington

Ward	Teddington
Road	Shaef Way
Location	W3W - ///pilots.thing.zebra
Species	Wild cherry (<i>Prunus avium</i>)
Height	12.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Teddington
Road	Vicarage Road
Location	Opposite 4
Species	Cherry (<i>Prunus sp.</i>)
Height	14.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies circled. [?]

Ward	Teddington
Road	Teddington Park Road
Location	Outside 61-63
Species	Apple (<i>Malus sp.</i>)
Height	9.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows cavity at base of trunk.

Ward	Teddington
Road	Arlington Road
Location	Outside 42-44
Species	Lebanese wild apple (<i>Malus trilobata</i>)
Height	8.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	Bark necrosis is present on the trunk of this tree; the decline of the trees vascular system correlates with dieback within the crown. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene



Image shows bark necrosis on trunk.

Ward	Teddington
Road	Cedar Road
Location	Adjacent to 42 High Street
Species	Sycamore (<i>Acer pseudoplatanus</i>)
Height	11.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree has an unacceptable amount of bark delamination at the base of the trunk which will cause dysfunction of the trees vascular system. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows bark delamination at bas of trunk.

Ward	Teddington
Road	Cedar Road
Location	Outside 28
Species	Apple (<i>Malus sp.</i>)
Height	9.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows fungal fruiting body circled at base of trunk.

Ward	Teddington
Road	Bolton Gardens
Location	Outside 29
Species	Apple (<i>Malus sp.</i>)
Height	6.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene

Ward	Teddington
Road	Church Road
Location	Outside 61/63
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Fungal fruiting bodies of the wood decay fungus <i>Laetiporus sulphurous</i> are present in the crown of this tree. This fungus causes a brown rot which can rapidly reduce wood strength and cause branch or whole tree failure through brittle fracture. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows fungal fruiting body (*Laetiporus sulphureus*) circled in crown.



Image shows fungal fruiting body (*Ganoderma* sp.) circled at base of trunk.

Ward	Teddington
Road	Bridgeman Road
Location	Outside 22/24
Species	Bird cherry (<i>Prunus padus</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows cavity with probe circled at base of trunk.

Ward	Teddington
Road	Shaef Way
Location	On Grass Area Outside 28
Species	Common laburnum (<i>Laburnum anagyroides</i>)
Height	4.5m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Teddington
Road	Coleshill Road
Location	Outside 2
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Teddington
Road	Coleshill Road
Location	Outside 18
Species	Chonosuki crab (<i>Malus tschonoskii</i>)
Height	8.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows fungal fruiting bodies circled at base of trunk.

Ward	Teddington
Road	Coleshill Road
Location	Outside 57/59
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Teddington
Road	Coleshill Road
Location	Outside 79
Species	Chonosuki crab (<i>Malus tschonoskii</i>)
Height	7.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows fungal fruiting bodies circled at base of trunk.

Ward	Teddington
Road	Coleshill Road
Location	Outside 57/59
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	Fruiting bodies of the decay fungus Turkey Tail (<i>Trametes versicolor</i>) are prolific on the trunk of this tree. This fungus causes a selective white rot of the wood and when prolific is indicative of wider physiological dysfunction. Crown die back corollate with the presence of these fungi. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene



Image shows fungal fruiting bodies circled at base of trunk.



Image shows probe showing decay circled at base of trunk.

Ward	Teddington
Road	Station Road
Location	Outside 59
Species	Grey alder (<i>Alnus incana</i>)
Height	4.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavity on the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows cavity on trunk.

Ward	Teddington
Road	Waldegrave Road
Location	Outside 95-97
Species	Alder (<i>Alnus sp.</i>)
Height	11.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Teddington
Road	Claremont Road
Location	Outside 37
Species	Purple leaf plum (<i>Prunus cerasifera</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene

Ward	Teddington
Road	Church Road
Location	Opposite 125
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Teddington
Road	Twickenham Road
Location	Outside 67
Species	Italian alder (<i>Alnus cordata</i>)
Height	16.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene



Image shows fungal fruiting bodies circled at base of trunk.

Whitton

Ward	Whitton
Road	Godfrey Avenue
Location	Outside 6/8
Species	Birch (<i>Betula sp.</i>)
Height	11.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows moribund tree in street scene.