



August 2026 - Reactive Tree Works Programme

Introduction

A survey of trees in the Kew, South Richmond and Whitton wards are currently being undertaken; this is being conducted by specialist arboricultural officers as part of the scheduled 4 yearly detailed inspection regime that has been devised for all Council highway and parks trees.

On a monthly basis the Council’s arboricultural officers undertake tree assessments that sit outside of the scheduled 4 yearly inspection programme, generally this is in response to customer enquiries.

These inspections take place to ensure that Council is compliant with the statutory duties which are highlighted within the [Council's Adopted Tree Policy](#).

Recent reactive inspections have identified the need for 106 individual tree work operations to take place. This work will now be issued to the Council’s Arborist Contractor KPS, for completion over the Autumn period.

Unfortunately, and as to be expected with surveys of a large treestock with specimen of varying age and condition, we have identified trees that can no longer be safely retained, and we will therefore be carrying out complete removal. The Council will aim to plant replacement trees during the next planting season which runs from November through to March; in some instances, this timing of planting may be affected by the available Highway Management resources that are required to repair disrupted pavements.

We will be erecting notices upon each tree being removed, alerting the public to the proposals giving sufficient time for residents to log enquiries. Prior to the removal taking place signage will be erected informing of a date of works, this is to make vehicle owners aware of the need to leave any parking space free to allow the works to proceed in a safe and timely manner.

The following pages provide the locations of each tree that is to be removed, in addition photographs and descriptions of the inspection findings have been provided.

These trees are exempt from the duty to consult.

Dated 02/09/2026

Contents

<u>Barnes</u>	3 - 7
<u>East Sheen</u>	8 - 9
<u>Fulwell and Hampton Hill</u>	10 - 11
<u>Kew</u>	12 - 24
<u>Mortlake and Barnes Common</u>	25
<u>North Richmond</u>	28 - 30
<u>South Richmond</u>	31 - 66
<u>South Twickenham</u>	67 - 69
<u>St Margarets and North Twickenham</u>	70 - 71
<u>Twickenham Riverside</u>	73
<u>Whitton</u>	74 - 113

Barnes

Ward	Barnes
Road	Lowther Road
Location	Outside 52-54
Species	Eleyi crabapple (<i>Malus x purpurea v eleyi</i>)
Height	6.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Barnes
Road	Parke Road
Location	Side of 9 Cumberland Road
Species	Norway maple (<i>Acer platanoides</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene

Ward	Barnes
Road	Gerard Road
Location	Opposite 38
Species	Wild cherry (<i>Prunus avium</i>)
Height	5.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	Barnes
Road	Gerard Road
Location	Outside 27/29
Species	Sargent's cherry (<i>Prunus sargentii</i>)
Height	8.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	Barnes
Road	Grange Road
Location	Adjacent to 56 Westmoreland Road main building
Species	Wild cherry (<i>Prunus avium</i>)
Height	5.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

East Sheen

Ward	Barnes
Road	Park Gate Gardens
Location	Outside 2
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	East Sheen
Road	Coval Road
Location	Outside 74 Temple Sheen Road
Species	Japanese flowering cherry (<i>Prunus Kanzan</i>)
Height	6.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Fulwell and Hampton Hill

Ward	Fulwell and Hampton Hill
Road	Connaught Road
Location	Outside 19
Species	Cherry (<i>Prunus sp.</i>)
Height	12.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies circled.

Kew

Ward	Kew
Road	Bushwood Road
Location	Outside 81
Species	Cherry (<i>Prunus sp.</i>)
Height	7.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows probe and fungal fruiting body circled.

Ward	Kew
Road	Thompson Avenue
Location	Outside 9
Species	Swedish Whitebeam (<i>Sorbus x intermedia</i>)
Height	5.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the trunk; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this particular species. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	Kew
Road	Thompson Avenue
Location	Outside 26
Species	Norway maple (<i>Acer platanoides</i>)
Height	13.5m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation by a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible damage on the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows damage on trunk circled.

Ward	Kew
Road	Thompson Avenue
Location	Outside 46
Species	Wild service tree (<i>Sorbus torminalis</i>)
Height	8.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Substantial wounding has occurred on the trunk and associated bark/vascular necrosis has taken place. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows damage on trunk circled.

Ward	Kew
Road	Thompson Avenue
Location	Outside 74/76
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	6.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows probe in cavity circled.

Ward	Kew
Road	Courtlands Avenue
Location	Outside 10
Species	Cherry (<i>Prunus sp.</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has an unacceptable movement at root plate and has become unstable. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.

Ward	Kew
Road	Chaucer Avenue
Location	Outside 15
Species	Norway maple (<i>Acer platanoides</i>)
Height	12.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus Ganoderma sp. is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Mortlake and Barnes Common

Ward	Mortlake and Barnes Common
Road	Cowley Road
Location	Outside 91
Species	Cherry (<i>Prunus sp.</i>)
Height	4.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Mortlake and Barnes Common
Road	Fitzgerald Avenue
Location	Outside 4/6
Species	Sargent's cherry (<i>Prunus sargentii</i>)
Height	7.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Mortlake and Barnes Common
Road	Buxton Road
Location	Outside 1
Species	European crab apple (<i>Malus sylvestris</i>)
Height	10.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

North Richmond

Ward	North Richmond
Road	Graemesdyke Avenue
Location	Outside 51
Species	Schmitt's Cherry (<i>Prunus x schmittii</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows probe and fungal fruiting bodies circled.

Ward	North Richmond
Road	Graemesdyke Avenue
Location	Outside 51
Species	Common lime (<i>Tilia x europaea</i>)
Height	10.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

South Richmond

Ward	South Richmond
Road	Berwyn Road
Location	Outside 20
Species	Apple (Malus sp.)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the main stem; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this particular species. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	South Richmond
Road	Berwyn Road
Location	Outside 32
Species	European Crab Apple (<i>Malus sylvestris</i>)
Height	9.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present within the crown. This fungus causes a simultaneous white rot which can result in the failure of branches and other tree parts in this species. Following a previous branch failure and the extent of fungal colonisation, removal is required to manage the risk of further failure and facilitate replanting.

Site images:



Image shows dead tree in street scene.



Image shows fungal fruiting body circled.



Image shows fracture wound from branch failure.

Ward	South Richmond
Road	Berwyn Road
Location	Outside 48 driveway
Species	Cherry Plum (<i>Prunus cerasifera</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation using a probe and a resonance test with a sounding hammer has revealed an unacceptable extent of decay beyond the visible cavities on the trunk. The presence of crown dieback is consistent with this condition. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity on trunk circled.

Ward	South Richmond
Road	Berwyn Road
Location	Adjacent to 585 Upper Richmond Road West
Species	Tibetan Cherry (<i>Prunus serrula</i>)
Height	4.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Orchard Rise
Location	Side of 35 Berwyn Road rear edge of building
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows in street scene.



Image shows cavity on trunk circled.

Ward	South Richmond
Road	Orchard Rise
Location	Opposite 7 Driveway
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	7.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	South Richmond
Road	Orchard Rise
Location	Outside 29 Sheen Common Drive front edge of building
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	6.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	Bark necrosis is present on the stem of this tree; the decline of the trees vascular system correlates with crown dieback. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.



Image shows bark necrosis on trunk.

Ward	South Richmond
Road	Orchard Rise
Location	Outside 3
Species	Japanese flowering cherry (<i>Prunus Kanzan</i>)
Height	4.5m
Physiological Condition	Fair
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is leaning into the road, creating an unacceptable obstruction to highway users. Removal is required to eliminate the obstruction and facilitate replanting.

Site images:



Image shows dead tree in street scene.



Image shows leaning trunk over pavement.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside East side of 29
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Fungal fruiting bodies of the cushion fungus (<i>Phellinus pomaceus</i>) is present throughout the crown of this tree. This fungus causes a crumbly white rot that commonly causes this species of tree to snap. Crown dieback also correlates with this. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies in crown circled.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside 46
Species	Cherry (<i>Prunus</i> sp.)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside 42
Species	Norway Maple (<i>Acer platanoides</i>)
Height	8.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has had trunk failure. Removal is required to prevent further natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows tear wound on trunk from union failure.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside 37
Species	Wild Crab Apple (<i>Malus sylvestris</i>)
Height	7.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present within the crown. This fungus causes a simultaneous white rot which can result in the failure of branches and other tree parts in this species. There is die back of the crown indicating poor condition which correlates with the presence of the pathogen. Removal is required to manage the risk of further failure and facilitate replanting.

Site images:



Image shows tree in street scene with die back of the crown.



Image shows fungal fruiting body in trunk circled.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside
Species	Pillar crab apple (<i>Malus tschonoskii</i>)
Height	10.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside 9
Species	Hawthorn (<i>Crataegus</i> sp.)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Sheen Common Drive
Location	Outside 8
Species	Hawthorn (<i>Crataegus sp.</i>)
Height	5.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has an unacceptable movement at root plate and has become unstable. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.

Ward	South Richmond
Road	Queens Crescent
Location	Outside 3
Species	Higan cherry (<i>Prunus subhirtella</i>)
Height	4.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Queens Crescent
Location	Outside 1 by driveway
Species	Higan cherry (<i>Prunus subhirtella</i>)
Height	4.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Fruiting bodies of the decay fungus Turkey Tail (<i>Tramates versicolor</i>) are prolific on the trunk of this tree. This fungus causes a selective white rot of the wood and when prolific is indicative of wider physiological dysfunction. This correlates with crown dieback and decay pockets on trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies and decay pocked in trunk circled.

Ward	South Richmond
Road	Hobart Place
Location	Outside 26
Species	Sycamore (<i>Acer pseudoplatanus</i>)
Height	14.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Fungal fruiting bodies of the decay pathogen <i>Kretzschmaria deusta</i> are present on the base of this tree. This fungus causes a white rot that can cause whole tree failure through a ceramic like fracture of the base. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene with dieback.



Image shows fungal fruiting body on trunk circled.



Image shows decay in trunk circled.

Ward	South Richmond
Road	Wakefield Road
Location	Opposite lamppost 004
Species	Pear (<i>Pyrus</i> sp.)
Height	5.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	South Richmond
Road	Paradise Road
Location	Outside 45
Species	Chanticleer pear (<i>Pyrus calleryana</i> 'Chanticleer')
Height	7.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Paradise Road
Location	Opposite junction to Mount Ararat Road
Species	Pillar crab apple (<i>Malus tschonoskii</i>)
Height	10.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Chester Avenue
Location	Opposite Chester Close flats 14-9
Species	Cherry (<i>Prunus</i> sp.)
Height	5.5m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Richmond
Road	Chester Avenue
Location	Outside Chester Close Flats 14-19
Species	Pillar crab apple (<i>Malus tschonoskii</i>)
Height	10.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body on trunk circled.

South Twickenham

Ward	South Twickenham
Road	Southfield Gardens
Location	Outside 2
Species	Silver birch (<i>Betula pendula</i>)
Height	15.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	South Twickenham
Road	Bonser Road
Location	Outside 54/56
Species	Bastard service tree (<i>Sorbus x thuringiaca</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	South Twickenham
Road	Stanley Road
Location	Opposite Lamppost 001
Species	Chanticleer Pear (<i>Pyrus calleryana</i>)
Height	7.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

St Margarets and North Twickenham

Ward	St Margarets and North Twickenham
Road	Rosslyn Road
Location	Outside 15
Species	Norway Maple (<i>Acer platanoides</i>)
Height	16.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavities at base of trunk.

Twickenham Riverside

Ward	Twickenham Riverside
Road	Morley Road
Location	Outside 2/4
Species	Field maple (<i>Acer campestre</i>)
Height	7.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Twickenham Riverside
Road	Alexandra Road
Location	Outside 19
Species	Japanese flowering cherry (<i>Prunus Kanzan</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Fair
Inspection findings/reason for exemption	Tree has raised and damaged root collar causing trip hazards and an unacceptable obstruction to the pavement making an impasse for prams & wheelchairs to safely pass. With no engineering solution available to resolve this issue, we are unable to meet our duties under the Equality Act 2010. For this reason, removal is required to manage risk and facilitate replanting.

Site images:



Image shows tree in street scene.

Whitton

Ward	Whitton
Road	Tranmere Road
Location	Outside 9
Species	Whitebeam (<i>Sorbus aria</i>)
Height	3.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Constance Road
Location	Outside 10a
Species	Whitebeam (<i>Sorbus aucuparia</i>)
Height	6.5m
Physiological Condition	Dead
Structural Condition	fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Constance Road
Location	Outside 109/111
Species	Downy birch (<i>Betula pubescens</i>)
Height	4.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Constance Road
Location	Outside 121
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	6.5m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has an unacceptable movement at root plate and has become unstable. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.

Ward	Whitton
Road	Constance Road
Location	Outside 58/60
Species	Silver birch (<i>Betula pendula</i>)
Height	4.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Constance Road
Location	Outside 61/63
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has an unacceptable movement at root plate and has become unstable. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.

Ward	Whitton
Road	Cypress Avenue
Location	Outside 1/3
Species	Bird cherry (<i>Prunus padus</i>)
Height	6.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Cypress Avenue
Location	Outside 42/44
Species	Bird cherry (<i>Prunus padus</i>)
Height	8.5m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity with probe circled.

Ward	Whitton
Road	Redway Drive
Location	Side of 2 Crane Way garden
Species	Bird cherry (<i>Prunus padus</i>)
Height	9.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Redway Drive
Location	Outside 18/20
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	3.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Redway Drive
Location	Outside 25/27
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	3.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Redway Drive
Location	Outside 29
Species	Whitebeam (<i>Sorbus aria</i>)
Height	3.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the in the primary union of the trunk. This fungus causes a simultaneous white rot which can cause snapping of tree parts in this particular species. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies circled.

Ward	Whitton
Road	Redway Drive
Location	Outside 18/20
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	3.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Redway Drive
Location	Outside 94
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	4.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Hazel Close
Location	Outside 26
Species	Cherry (<i>Prunus sp.</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Hazel Close
Location	Outside 99
Species	Cherry (<i>Prunus sp.</i>)
Height	6.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	The Ridge
Location	Outside 7
Species	Cherry (Prunus sp.)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	The Ridge
Location	Outside 7
Species	Cherry (Prunus sp.)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is progressively leaning over the pavement and is creating an unacceptable obstruction to pedestrians. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows leaning tree in street scene.

Ward	Whitton
Road	Crane Way
Location	Outside 1
Species	Pear (<i>Pyrus sp.</i>)
Height	9.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Warren Road
Location	Outside 61
Species	Norway maple (<i>Acer platanoides</i>)
Height	12.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Warren Road
Location	Outside 19/21
Species	Italian alder (<i>Alnus cordata</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Godfrey Avenue
Location	Adjacent to 2 Alton Gardens main building
Species	Norway maple (<i>Acer platanoides</i>)
Height	15.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	Whitton
Road	Godfrey Avenue
Location	Outside 48/50
Species	Cherry (<i>Prunus sp.</i>)
Height	5.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity at base of trunk circled.

Ward	Whitton
Road	Alton Gardens
Location	Outside 47/49
Species	Birch (<i>Betula sp.</i>)
Height	10.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Chase Gardens
Location	Adjacent to 25 Kneller Road main building
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	4.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe has revealed an unacceptable amount of decay beyond the visible cavities at on the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity on trunk circled.

Ward	Whitton
Road	Chase Gardens
Location	Outside 21/23
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	3.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Kendrey Gardens
Location	Side of 7 Kneller Road
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	6.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Rosebine Avenue
Location	Adjacent to lamppost 001
Species	Wild Cherry (<i>Prunus avium</i>)
Height	10.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Rosebine Avenue
Location	Side of 68 Gladstone Avenue midpoint of garden
Species	Cherry (<i>Prunus sp.</i>)
Height	5.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Collingwood Close
Location	Outside 31
Species	Cherry (<i>Prunus sp.</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has cracked, peeling bark indicating necrosis and dysfunction of the trees vascular system. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows bark damage on trunk.

Ward	Whitton
Road	Collingwood Close
Location	Outside 33/35
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	5.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Prospect Crescent
Location	Outside 105/107
Species	Apple (Malus sp.)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Whitton
Road	Bridge Way
Location	Outside 9
Species	Wild cherry (<i>Prunus avium</i>)
Height	8.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Warren Road
Location	Opposite 47
Species	Norway maple (<i>Acer platanoides</i>)
Height	9.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Whitton
Road	Rosebine Avenue
Location	Side of 70 Gladstone Avenue midpoint of garden
Species	Cherry (<i>Prunus sp.</i>)
Height	7.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.