



June 2026 phase 1 – HW Reactive Tree Works Programme

Introduction

A survey of trees in Teddington and Hampton wards have been undertaken; this is being conducted by specialist arboricultural officers as part of the scheduled 4 yearly detailed inspection regime that has been devised for all Council highway and parks trees.

On a monthly basis the Council’s arboricultural officers undertake tree assessments that sit outside of the scheduled 4 yearly inspection programme, generally this is in response to customer enquiries.

These inspections take place to ensure that Council is compliant with the statutory duties which are highlighted within the [Council's adopted Tree Policy](#).

Recent reactive inspections have identified the need for 37 individual tree work operations to take place. This work will now be issued to the Council’s arborist contractor KPS, for completion over the Summer period.

Unfortunately, and as to be expected with surveys of a large treestock with specimen of varying age and condition, we have identified trees that can no longer be safely retained, and we will therefore be carrying out complete removal. The Council will aim to plant replacement trees during the next planting season which runs from November through to March; in some instances, this timing of planting may be affected by the available Highway Management resources that are required to repair disrupted pavements.

We will be erecting notices upon each tree being removed, alerting the public to the proposals giving sufficient time for residents to log enquiries. Prior to the removal taking place signage will be erected informing of a date of works, this is to make vehicle owners aware of the need to leave any parking space free to allow the works to proceed in a safe and timely manner.

The following pages provide the locations of each tree that is to be removed, in addition photographs and descriptions of the inspection findings have been provided.

Dated 27.06.2026

Contents

<u>Fulwell and Hampton Hill</u>	3
<u>Hampton</u>	4 - 25
<u>Heathfield</u>	26
<u>Kew</u>	27 - 29
<u>Teddington</u>	30 - 33
<u>Twickenham Riverside</u>	34 - 35
<u>West Twickenham</u>	36
<u>Whitton</u>	37

Fulwell and Hampton Hill

Ward	Fulwell and Hampton Hill
Road	Princes Road
Location	Outside 36
Species	Silver birch (<i>Betula pendula</i>)
Height	15.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Hampton

Ward	Hampton
Road	Ormond Drive
Location	Outside 84-86
Species	Apple (<i>Malus sp.</i>)
Height	7.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma</i> sp. is present on the base of the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test revealed an unacceptable degree of decay in the which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	Hampton
Road	Warwick Close
Location	Opposite 26 ///exams.fits.moss
Species	Sycamore (<i>Acer pseudoplatanus</i>)
Height	10.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:




Image shows moribund tree in street scene.

Ward	Hampton
Road	Warwick Close
Location	Opposite 4A
Species	Elm (<i>Ulmus sp.</i>)
Height	6.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows Dead tree in street scene.

Ward	Hampton
Road	Howard Close
Location	Opposite 1/3
Species	Sweet chestnut (<i>Castanea sativa</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Hampton
Road	Ormond Crescent
Location	Outside
Species	Cherry (<i>Prunus sp.</i>)
Height	7.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Wounding to the main trunk has resulted in bark and vascular necrosis and crown dieback. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows wound on trunk circled.

Ward	Hampton
Road	Ormond Crescent
Location	Outside 3
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	7.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test revealed an unacceptable degree of decay in the which correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	Hampton
Road	Parrs Place
Location	Outside 5
Species	Birch (<i>Betula sp.</i>)
Height	10.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree has bleeding bark on the main stem with associated bark necrosis, which correlates with dieback in the crown. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.



Image shows bleeding bark on trunk

Ward	Hampton
Road	Chestnut Avenue
Location	Outside 4/6
Species	Chestnut (<i>Aesculus sp.</i>)
Height	11.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Hampton
Road	Malvern Road
Location	Outside 55-57
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Ward	Hampton
Road	Falcon Road
Location	Adjacent to 163 Broad Lane- the Garage
Species	Lime (<i>Tilia sp.</i>)
Height	2.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Hampton
Road	Falcon Road
Location	Outside 37-39
Species	Apple (<i>Malus sp.</i>)
Height	5.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity at base of trunk circled.



Image shows cavity at base of trunk circled.

Ward	Hampton
Road	Ripley Road
Location	Opposite 2-4
Species	Hornbeam (<i>Carpinus betulus</i> 'Fastigiata')
Height	8.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Hampton
Road	Broad Lane
Location	Outside 48
Species	English Oak (<i>Quercus robur</i>)
Height	16m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.



Image shows moribund tree in street scene.

Ward	Hampton
Road	Holly Bush Lane
Location	Outside 37
Species	Common Ash (<i>Fraxinus excelsior</i>)
Height	16.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree has cracked, peeling bark indicating necrosis and dysfunction of the trees vascular system which correlates with over 50% of the crown being dead. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.



Image shows bark delamination on lower trunk.

Ward	Hampton
Road	Douai Grove
Location	Outside 20
Species	Wild cherry (<i>Prunus avium</i>)
Height	8.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Heathfield

Ward	Heathfield
Road	Glasbrook Avenue
Location	Outside 13/15
Species	Norway maple (<i>Acer platanoides</i>)
Height	10.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Kew

Ward	Kew
Road	Marksbury Avenue
Location	Outside 46
Species	Cherry (<i>Prunus sp.</i>)
Height	7.5m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Kew
Road	Defoe Avenue
Location	Outside 1
Species	Silver birch (<i>Betula pendula</i>)
Height	8.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Kew
Road	The Avenue
Location	Outside 76/78
Species	Cherry (<i>Prunus sp.</i>)
Height	4.0m
Physiological Condition	Good
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is leaning across the footway to an unacceptable degree and causing an unreasonable obstruction. Removal is required to manage the unacceptable risk of pedestrian injury and facilitate replanting

Site images:



Image shows leaning tree in street scene.

Teddington

Ward	Teddington
Road	Park Road
Location	Opposite 39
Species	Horse Chestnut (<i>Aesculus hippocastanum</i>)
Height	16.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A detailed investigation was conducted on the trunk of this tree using sonic tomography. The results of the detailed inspection identify significant decay, as shown in the light-coloured areas in the image of the cross-section of the stem below, spreading to the sound wood shown as darker-coloured areas. Removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows tree in street scene.




Image shows results from decay detection investigation at the base of the tree – green, blue and purple indicate decayed wood

Ward	Teddington
Road	Queens Road
Location	Outside 115
Species	Silver birch (<i>Betula pendula</i>)
Height	14.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Teddington
Road	Clarence Road
Location	Outside 65
Species	Chestnut (<i>Aesculus sp.</i>)
Height	8.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund with over 50% of the crown being dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows moribund tree in street scene

Twickenham Riverside

Ward	Twickenham Riverside
Road	Lebanon Park
Location	Outside 53
Species	Wild cherry (<i>Prunus avium</i>)
Height	10.0m
Physiological Condition	Dead
Structural Condition	Poor
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:




Image shows dead tree in street scene.

Ward	Twickenham Riverside
Road	Heath Road
Location	Outside 53
Species	Ash (<i>Fraxinus sp.</i>)
Height	7.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

West Twickenham

Ward	West Twickenham
Road	Fifth Cross Road
Location	Opposite 6
Species	English Oak (<i>Quercus robur</i>)
Height	19.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene.

Whitton

Ward	Whitton
Road	Chase Gardens
Location	Adjacent to 23 Kneller Road rear garden
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is leaning across the footway to an unacceptable degree and causing an unreasonable obstruction. Removal is required to manage the unacceptable risk and facilitate replanting

Site images:



Image shows tree in street scene.