



September 2026 – Highways Reactive Tree Works Programme

Introduction

A survey of trees in the Whitton, Heathfield and Ham, Petersham and Richmond Riverside wards are currently being undertaken; this is being conducted by specialist arboricultural officers as part of the scheduled 4 yearly detailed inspection regime that has been devised for all Council highway and parks trees.

On a monthly basis the Council’s arboricultural officers undertake tree assessments that sit outside of the scheduled 4 yearly inspection programme, generally this is in response to customer enquiries.

These inspections take place to ensure that Council is compliant with the statutory duties which are highlighted within the [Council's Adopted Tree Policy](#).

Recent reactive inspections have identified the need for 79 individual tree work operations to take place. This work will now be issued to the Council’s Arborist Contractor KPS, for completion over the Autumn period.

Unfortunately, and as to be expected with surveys of a large treestock with specimen of varying age and condition, we have identified trees that can no longer be safely retained, and we will therefore be carrying out complete removal. The Council will aim to plant replacement trees during the next planting season which runs from November through to March; in some instances, this timing of planting may be affected by the available Highway Management resources that are required to repair disrupted pavements.

We will be erecting notices upon each tree being removed, alerting the public to the proposals giving sufficient time for residents to log enquiries. Prior to the removal taking place signage will be erected informing of a date of works, this is to make vehicle owners aware of the need to leave any parking space free to allow the works to proceed in a safe and timely manner.

The following pages provide the locations of each tree that is to be removed, in addition photographs and descriptions of the inspection findings have been provided.

These trees are exempt from the duty to consult.

Dated 18.9.2026

Contents

<u>Ham, Petersham and Richmond Riverside</u>	3 - 42
<u>Heathfield</u>	43 - 56
<u>Kew</u>	52 - 15
<u>North Richmond</u>	57
<u>Whitton</u>	57 - 81

Ham, Petersham and Richmond Riverside

Ward	Ham, Petersham and Richmond Riverside
Road	Sandy Lane
Location	Opposite Grey Court Stables
Species	Wild Cherry (<i>Prunus avium</i>)
Height	8.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene

Ward	Ham, Petersham and Richmond Riverside
Road	Sandy Lane
Location	Outside Grey Court School opposite lamp post 019
Species	Common ash (<i>Fraxinus excelsior</i>)
Height	8.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene

Ward	Ham, Petersham and Richmond Riverside
Road	Meadlands Drive
Location	Outside 16
Species	Norway maple (<i>Acer platanoides</i>)
Height	15.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree in street scene

Ward	Ham, Petersham and Richmond Riverside
Road	Meadlands Drive
Location	Outside 82
Species	Birch (<i>Betula sp.</i>)
Height	2.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene

Ward	Ham, Petersham and Richmond Riverside
Road	Woodlawn Crescent
Location	Outside 25
Species	Silver birch (<i>Betula pendula</i>)
Height	9.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Petersham Close
Location	Opposite 2&6
Species	Wild cherry (<i>Prunus avium</i>)
Height	11.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows tree fungal fruiting body at base of trunk.



Image shows tree fungal fruiting bodies at base of trunk.

Ward	Ham, Petersham and Richmond Riverside
Road	Petersham Close
Location	Outside 4&8
Species	Bird cherry (<i>Prunus padus</i>)
Height	7.5m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. Crown dieback is evident and correlates with the presence of the decay fungi. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.



Image shows tree fungal fruiting body at base of trunk.

Ward	Ham, Petersham and Richmond Riverside
Road	Buckingham Road
Location	Opposite 37
Species	Cherry (<i>Prunus sp.</i>)
Height	4.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Buckingham Road
Location	Outside 25
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	10.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus Ganoderma sp. is present on the trunk. Colonisation by this fungus can result in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow. A resonance test with a sounding hammer and probe has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body at base of trunk.



Image shows probe highlighting cavity at base of trunk.

Ward	Ham, Petersham and Richmond Riverside
Road	Buckingham Road
Location	Outside 65
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	8.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Arlington Road
Location	Outside 8
Species	Wild cherry (<i>Prunus avium</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Lauderdale Drive

Location	Outside 67 at end of road on substation roadside
Species	Common ash (<i>Fraxinus excelsior</i>)
Height	17.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the main trunk; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this particular species. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:




Image shows tree in street scene.



Image shows fungal fruiting bodies circled.

Ward	Ham, Petersham and Richmond Riverside
Road	Lauderdale Drive
Location	Outside 65
Species	Wild cherry (<i>Prunus avium</i>)
Height	6.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
------	---------------------------------------

Road	Lauderdale Drive
Location	Outside 63
Species	Wild cherry (<i>Prunus avium</i>)
Height	4.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Lauderdale Drive
Location	Outside 53
Species	Wild cherry (<i>Prunus avium</i>)
Height	4.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Sandy Lane
Location	Outside 14
Species	Common Oak (<i>Quercus robur</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Good
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Arlington Road
Location	Adjacent to 35 Sandy Lane rear end of garden
Species	Wild cherry (<i>Prunus avium</i>)
Height	6.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Meadow Close
Location	On grass verge opposite side wall of 6
Species	Holly (<i>Ilex sp.</i>)
Height	7.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Cedar Heights
Location	Outside 182
Species	Wild cherry (<i>Prunus avium</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Ashfield Close
Location	Outside 25
Species	European crab apple (<i>Malus sylvestris</i>)
Height	7.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present in cavity in primary union. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer and probe has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body circled.

Ward	Ham, Petersham and Richmond Riverside
------	---------------------------------------

Road	Cedar Heights
Location	Outside 11
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavity on a historic tear wound on trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity on historic tear wound.

Ward	Ham, Petersham and Richmond Riverside
Road	Cardigan Road
Location	Opposite 22
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	9.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows dead tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
------	---------------------------------------

Road	Ham Street
Location	Opposite lamppost 018 adjacent to Beauford House
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	15.0m
Physiological Condition	Poor
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show tree in street scene.



Images show cavity at base of trunk circled.

Ward	Ham, Petersham and Richmond Riverside
------	---------------------------------------

Road	Back Lane
Location	Outside 13
Species	Swedish whitebeam (<i>Sorbus x intermedia</i>)
Height	6.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the trunk; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this species

Site images:



Images show tree in street scene.



Images show fungal fruiting body on truck.

Ward	Ham, Petersham and Richmond Riverside
Road	Broughton Avenue
Location	Outside 22-24
Species	German whitebeam (<i>Sorbus x thuringiaca</i>)
Height	8.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavity on the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show tree in street scene.



Images show cavity on trunk circled.

Ward	Ham, Petersham and Richmond Riverside
Road	Ashburnham Road

Location	Outside 15-17
Species	Lime (<i>Tilia sp.</i>)
Height	9.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show tree in street scene.



Images show fungal fruiting body circled.

Ward	Ham, Petersham and Richmond Riverside
Road	Watermill Close
Location	Outside 10-12
Species	Golden robinia (<i>Robinia pseudoacacia Frisia</i>)
Height	13.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show moribund tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Watermill Close
Location	Outside 6-8
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	5.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show dead tree in street scene.

Ward	Ham, Petersham and Richmond Riverside
Road	Watermill Close
Location	Outside 2
Species	Rowan (<i>Sorbus aucuparia</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavity at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show tree in street scene.



Images show cavity and probe circled.

Heathfield

Ward	Heathfield
Road	Montrose Avenue
Location	Outside 25
Species	Cherry plum (<i>Prunus cerasifera</i>)
Height	5.0m
Physiological Condition	Good
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity at base of trunk.

Ward	Heathfield
Road	Strathearn Avenue
Location	Opposite 6
Species	Ornamental crabapple (<i>Malus sp.</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the species Shaggy Polypore (<i>Inonotus hispidus</i>) is present on the trunk; this fungus causes a simultaneous white rot which can cause snapping of tree parts in this species; removal is required to prevent natural failure and facilitate replanting

Site images:



Images show tree in street scene.



Image shows fungal fruiting bodies at base of trunk circled.

Ward	Heathfield
Road	Woodlawn Crescent
Location	Opposite 68
Species	Birch (<i>Betula sp</i>)
Height	15.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Heathfield
Road	Powder Mill Lane
Location	Opposite 79
Species	Tulip tree (<i>Liriodendron tulipifera</i>)
Height	6.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows tree in street scene.

Ward	Heathfield
Road	Powder Mill Lane
Location	Outside 195
Species	Norway Maple (<i>Acer platanoides</i>)
Height	14.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer and probe has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body and probe highlighting decay circled.

Ward	Heathfield
Road	Powder Mill Lane
Location	Opposite 179
Species	Pear (<i>Pyrus sp.</i>)
Height	7.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Heathfield
Road	Bird Walk
Location	Outside 190
Species	Wild cherry (<i>Prunus avium</i>)
Height	12.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	Investigation with a probe and a resonance test with a sounding hammer has revealed an unacceptable amount of decay beyond the visible cavities at the base of the trunk. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows cavity on trunk circled.

Ward	Heathfield
Road	Hanworth Road
Location	Outside 666-668
Species	Plane (<i>Platanus sp.</i>)
Height	5.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure and facilitate replanting

Site images:



Image shows dead tree in street scene.

Ward	Heathfield
Road	Waverley Avenue
Location	Outside of 176/178
Species	Norway Maple (<i>Acer pseudoplatanus</i>)
Height	12.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	Substantial wounding has occurred on the trunk of this tree and associated bark/vascular necrosis has taken place. Removal is required to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Images show tree in street scene.



Images show delamination of bark on trunk.

North Richmond

Ward	North Richmond
Road	Pagoda Avenue
Location	Outside 46
Species	Silver birch (<i>Betula pendula</i>)
Height	7.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows dead tree in street scene.

Whitton

Ward	Whitton
Road	Old Manor Drive
Location	Adjacent to 215 Whitton Dene Main building
Species	Cherry Plum (<i>Prunus cerasifera</i>)
Height	8.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has fungal fruiting bodies of the cushion fungus (<i>Phellinus pomaceus</i>) present throughout the crown of this tree. This fungus causes a crumbly white rot that commonly causes this species of tree to snap. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies in crown circled.



Image shows fungal fruiting bodies on stem circled.

Ward	Whitton
Road	Old Manor Drive
Location	Adjacent to 215 Whitton Dene Rear garden
Species	Cherry Plum (<i>Prunus cerasifera</i>)
Height	4.5m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has substantial wounding at the base of the trunk, with vertical cracking on exposed heartwood evident within the wound. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows wounding and cracking on trunk circled.

Ward	Whitton
Road	Colonial Avenue
Location	Outside 21/23
Species	Birch (<i>Betula sp.</i>)
Height	4.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image moribund tree shows in street scene.

Ward	Whitton
Road	Rydal Gardens
Location	Outside 19/21
Species	Cherry Plum (<i>Prunus cerasifera</i>)
Height	5.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	This tree has fungal fruiting bodies of the cushion fungus (<i>Phellinus pomaceus</i>) present throughout the crown of this tree. This fungus causes a crumbly white rot that commonly causes this species of tree to snap. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows tree in street scene.



Image shows fungal fruiting bodies in crown circled.



Image shows fungal fruiting bodies on stem circled.

Ward	Whitton
Road	Rydal Gardens
Location	Outside 61/63
Species	Cherry (<i>Prunus sp.</i>)
Height	6.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows wounding and cracking on trunk.



Image shows fungal fruiting body circled.

Ward	Whitton
Road	Derwent Road
Location	Outside 6
Species	Apple (<i>Malus sp.</i>)
Height	5.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Coniston Road
Location	Outside 31
Species	Birch (<i>Betula sp.</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Derwent Road
Location	Outside 4
Species	Common beech (<i>Fagus sylvatica</i>)
Height	2.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Grasmere Avenue
Location	Outside 16/18
Species	Cherry (<i>Prunus sp.</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Camellia Place
Location	Adjacent to 137-139 Constance Road
Species	Birch (<i>Betula sp.</i>)
Height	5.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image moribund tree shows in street scene.

Ward	Whitton
Road	Camellia Place
Location	Opposite 6
Species	Field maple (<i>Acer campestre</i>)
Height	7.5m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image shows moribund tree shows in street scene.

Ward	Whitton
Road	Hospital Bridge Road
Location	Adjacent to 1 Springfield Road
Species	Norway maple (<i>Acer platanoides</i>)
Height	8.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image moribund tree shows in street scene.

Ward	Whitton
Road	Hospital Bridge Road
Location	Adjacent to 1 Springfield Road
Species	Norway maple (<i>Acer platanoides</i>)
Height	6.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is moribund; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Hospital Bridge Road
Location	Outside 133
Species	Norway maple (<i>Acer platanoides</i>)
Height	12.0m
Physiological Condition	Poor
Structural Condition	Fair
Inspection findings/reason for exemption	Fungal fruiting bodies of the decay fungi 'Honey fungus' <i>Armillaria</i> sp. are present at the base of this tree. Colonisation by this fungus causes a white rot of the roots and butt that can cause entire tree failure. Crown dieback could correlate with the parasite present. Removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image tree shows in street scene.



Ward	Whitton
Road	Nelson Road
Location	Outside 302
Species	Norway maple (<i>Acer platanoides</i>)
Height	4.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Nelson Road
Location	On grass verge outside 355
Species	American Lime (<i>Tilia americana</i>)
Height	4.0m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Whitton Way
Location	Outside 32/34
Species	Apple (Malus sp.)
Height	7.5m
Physiological Condition	Dead
Structural Condition	Fair
Inspection findings/reason for exemption	This tree is dead; removal is required to prevent natural failure, manage risk, and facilitate replanting

Site images:



Image dead tree shows in street scene.

Ward	Whitton
Road	Whitton Waye
Location	On grass area at North side of road opposite 57
Species	Black Locust (Robinia pseudoacacia)
Height	18.0m
Physiological Condition	Fair
Structural Condition	Poor
Inspection findings/reason for exemption	A fungal fruiting body of the decay fungus <i>Ganoderma sp.</i> is present on the trunk. Colonisation by this fungus results in white rot affecting the stem and root system, which can lead to structural failure through fracture or windthrow A resonance test with a sounding hammer has revealed an unacceptable amount of decay around the bracket. Removal of the tree is recommended to prevent natural failure, manage risk, and facilitate replanting.

Site images:



Image shows tree in street scene.



Image shows fungal fruiting body and probe circled.